Sale Name: QUALITY ESTATES & AMAZON GENERAL MERCHANDISE - ONLINE AUCTION - JUNE 14th, 2023

LOT 28 - Upgraded 5301EL1001A Dryer Heating Element Assembly by Sikawai Fit for LG Ken-more Dryers Replaces 1377645 AP5072170 AP4439759 PS3527791 PS3527790 EAP3527791



Description

- PACKAGE INCLUDES -- 5301EL1001A Dryer Heating Element Assembly includes housing, wiring, thermostats, and heater. Fits Most LG Ken-more models Dryer
- REPLACES PARTS -- 5301EL1001A Clothes Dryer Heater Assembly Replaces parts number: 5301EL1001A, 5301EL1001J, 5301EL1001E, 5301EL1001G, 5301EL1001H, 5301EL1001S, 5301EL1001U, 5301EL1001W, AEG72910301, AP4439759, 1377645, PS3527791, EAP3527791
- SIKAWAI YOUR MONEY SAVING EXPERT -- At Sikawai, we are committed to providing economical DIY repair solutions for your goods to make your life simple, comfortable and convenient. 5301EL1001A Dryer Heating Element Assembly itself is very easy to install, requiring only 2 screws. It only takes a few minutes to install when you watch the installation video on Youtube. You'll save hundreds of dollars on a trip to your local repair store and get a working dryer again.
- REPAIR SYMPTOMS -- It can solve the problems as follows: not drying properly, takes too long to dry, too much heat, not enough heat. To confirm if there is a problem with the heating element, unplug the dryer at the onset of symptoms

Quantity: 1



